



DESIGN <i>[Signature]</i>	DRAWN BY RF	<b>DART AEROSPACE LTD</b> HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. DSI 9339	REV. A SHEET 1 OF 1
DATE 06.06.07		TITLE 407 AFT X-TUBE SUPPORT SUBSTITUTION NTS	
A	06.06.07	NEW ISSUE	

## **DART SERVICE INSTRUCTION**

**TO AMEND INSTALLATION INSTRUCTION IIN-D206-667 REV. C OR EARLIER**

REF. CANADIAN STC: SH01-5 ISSUE 2/3

REF. FAA STC: SR01304NY

It is acceptable to replace the Dart D2894-1 Center Support (1) and MS21920-24 Clamps (2) installed on the D407-667-205 Aft Crosstubes with BHT P/N 400-052-006-101 Upper Support (1), 205-050-133-101 Lower Support (1), and 205-050-134-001 U-bolts (2). These parts should be installed per section 32-28 of BHT-407-MM-5. Inspect the Dart crosstube for damage in accordance with ICA-D206-667 before installation of the Bell parts. Repair and re-finish the crosstube as required per ICA-206-667.

CANADA  
DEPARTMENT OF TRANSPORT  
AIRCRAFT CERTIFICATION  
BRANCH  
DAO # 01-O-01

### **APPROVED**

BY: *[Signature]*  
D. SHEPHERD (DE # 02)

DATE: 06.06.07  
CERT. NO.: SH01-5  
ISSUE NO.: 2/3

**Copyright © 2006 by DART AEROSPACE LTD**

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.